




RUSS



x1



F x10
M8 x80




B x6
M8 x55



A x18



C x6
M6 x60



R x4



W x4
M8 x80



K x6



H x10




G x10




x1


1.




2.




3.




4.




5.




6.




7.



8.



9.



10.

